

Inspection Photos
Location Name: HSR-Lost Creek 16-29
Location ID: 330672



Photo 1 – Separator, ECD and Gas Meter



Photo 2 – Tank Battery

Inspection Photos
Location Name: HSR-Lost Creek 16-29
Location ID: 330672



Photo 3 – Weeds at Pumping Unit



Photo 4 – Stained Soil at Wellhead