

Inspection Photos

12/5/2022

Operator: UTAH GAS OP LTD DBA UTAH GAS

CORP - 10539

Location #322420

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322420



December 5, 2022



December 5, 2022

Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322420



Photo 2: See comment under photo 1.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322420



Photo 3: Photo shows tank battery facility on the east end of the Location. Facility signage not observed at battery.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322420



Photo 4: Photo shows wellhead on the southwest end of the Location. Photo shows signage missing at the wellhead. Signage observed on site observed adjacent to pipe equipment next to metershed.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322420



Photo 5: Photo shows solar equipment and 5 SVE wells associated with remediation project #9341.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322420



December 5, 2022



December 5, 2022

Photo 6: Photos 6-7 show anchors on the Location missing required marking.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location #322420



Photo 7: See comment under photo 6.