

Final Reclamation and Stormwater Inspection

Date: 12/01/2022

Operator: FUNDARE RESOURCES OPERATING COMPANY- 10773

Location ID: 420175

Inspection Document #: 696105626

Weld County, CO

SWNE Section 36 T10N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Terrace #36-32M
Location ID: 420175



Photo 1. Taken from the southern portion of the location, facing west. Photo illustrates debris (e.g. netting) observed on location that needs to be removed and properly disposed of.

Inspection Photos
Location Name: Terrace #36-32M
Location ID: 420175



Photo 2. Taken near the southeastern corner of the location, facing west. See comments in Photo 1.



Photo 3. Close up photo of russian thistle, key for scale. The location consisted predominantly of russian thistle and bare soil. Some desirable vegetation was also observed in sparse amounts.

Inspection Photos
Location Name: Terrace #36-32M
Location ID: 420175




Photo 4. Taken from the southeast corner, facing north. Photo illustrates presence of bare soil resulting from lack of uniform vegetation cover.

Inspection Photos
Location Name: Terrace #36-32M
Location ID: 420175



Photo 5. Taken from the northwest corner, facing northeast. Photo illustrates presence of russian thistle throughout the location.

Inspection Photos
Location Name: Terrace #36-32M
Location ID: 420175



Photo 1. Reference area photo taken west of location, facing north. Reference area is predominantly buffalo grass with sand sagebrush and fourwing saltbrush also identified.