

Final Reclamation and Stormwater Inspection

Date: 12/01/2022

Operator: FUNDARE RESOURCES OPERATING COMPANY - 10773

Location ID: 330859

Inspection Document #: 696105634

Weld County, CO

NWNE Section 31 T10N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Walker #1
Location ID: 330859



Photo 1. Taken from the southern access road entrance, facing northwest. Photo illustrates the access road has not revegetated and does not meet 1004 reclamation standards. Undesirable vegetation (e.g. russian thistle and kochia) was observed throughout the majority of the former access road.

Inspection Photos
Location Name: Walker #1
Location ID: 330859



Photo 2. Close-up photo of t-post found partially buried on former well location.

Inspection Photos
Location Name: Walker #1
Location ID: 330859



Photo 3. Close-up photo of russian thistle observed on location.

Inspection Photos
Location Name: Walker #1
Location ID: 330859



Photo 4. Taken from southwestern portion of location, facing northeast. Photo illustrates the location does not meet 1004 rules and requirements for vegetation establishment; undesirable vegetation (e.g. russian thistle and kochia) observed throughout the reclaimed area.