

# Final Reclamation and Stormwater Inspection

Date: 12/01/2022

Operator: FUNDARE RESOURCES OPERATING  
COMPANY- 10773

Location ID: 330800

Inspection Document #: 696105638

Weld County, CO

NWSW Section 29 T10N R58W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: UHL #1  
Location ID: 330800



**Photo 1.** Facing east from county road. Oil and gas equipment (pipeline risers, cages/barriers) remain on location, outlined in red. Two track road on left of photo appears to be used by surface owner.



Inspection Photos  
Location Name: UHL #1  
Location ID: 330800



**Photo 2.** Facing east from well location. Photo illustrates presence of undesirable vegetation, predominantly russian thistle with minute amounts of desirable vegetation also observed.



Inspection Photos  
Location Name: UHL #1  
Location ID: 330800



**Photo 3.** Facing east from well location. All oil and gas equipment needs to be removed from location in order to comply with 1004 Rules.