

Final Reclamation and Stormwater Inspection

Date: 12/01/2022

Operator: FUNDARE RESOURCES OPERATING
COMPANY- 10773

Location ID: 330979

Inspection Document #: 696105642

Weld County, CO

NWNW Section 29 T10N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Taken north of the tank battery, facing east. Photo illustrates that the access road has been reclaimed and revegetated with desirable species. Red outline indicates pipeline markers that need to be removed.

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 2. Taken from the southern portion of the well location, facing north. Photo illustrates the location has been reclaimed with presence of desirable vegetation (e.g. buffalo grass, sand drop seed, etc). The red outlined pipeline markers need to be removed.



Photo 3. Taken from the tank battery location, facing northeast. Photo illustrates the location has not revegetated with desirable species as evidenced by russian thistle and areas of bare soil. Red outline indicates pipeline markers that need to be removed.

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 4. Facing east, see comments in Photo 3.

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 5. Close-up photo of bare soil and russian thistle.