

Inspection Photos

API: 071-09011

Operator: WAPITI OPERATING LLC

Inspection Date: 12/7/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09011 | Date: 12/7/2022

Inspection Photos



Photo 1. There are noxious weeds along the access road that need to be controlled. The red arrow points to List B noxious weed - Houndstongue.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09011 | Date: 12/7/2022

Inspection Photos



Photo 2. Facing northwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09011 | Date: 12/7/2022