

Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334900

Location Name: PITMAN-67S93W/13SWNW

Inspection Document #: 702801008

Garfield County, CO

SWNW Section 13 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PITMAN-67S93W/13SWNW
Location ID: 334900



Photo 1. Photos show production areas. Note sign installed at tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801008

Inspection Photos

Location Name: PITMAN-67S93W/13SWNW

Location ID: 334900



Photo 2. Photos show production areas. Caps have been installed on separator lines.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801008

Inspection Photos

Location Name: PITMAN-67S93W/13SWNW

Location ID: 334900



Photo 3. Photo shows interim areas at the south of the location are vegetated with perennial grasses.



Photo 4. Photo shows interim areas at the northeast of the location are vegetated with perennial grasses



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801008

Inspection Photos

Location Name: PITMAN-67S93W/13SWNW

Location ID: 334900



Photo 5. Photo taken to the northeast of the location shows the area of remediation #5169. Vegetation consists of weedy annuals.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801008