

Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334930

Location Name: CEDAR SPRINGS RANCH-67S93W/2NESW

Inspection Document #: 702801019

Garfield County, CO

NESW Section 2 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CEDAR SPRINGS RANCH-67S93W/2NESW
Location ID: 334930



Photo 1. Photos show production areas. Note tank battery sign has been installed (left). Potential leak observed at well (right).

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/2NESW

Location ID: 334930



Photo 2. Photo shows production areas. Note improperly abandoned flowline riser not locked out/tagged out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801019

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/2NESW

Location ID: 334930



Photo 3. Photos show interim areas to the north (left) and south (right) are dominated by introduced perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801019