

Inspection Photos
Location Name: Lost Creek #5
Location ID: 331882




Photo 1 – Wellhead



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Lost Creek #5
Location ID: 331882



Photo 3 – Separator



Photo 4 – Trash has been picked up

Inspection Photos
Location Name: Lost Creek #5
Location ID: 331882



Photo 5 – Content Label




Photo 6 – Unmarked Riser

Inspection Photos
Location Name: Lost Creek #5
Location ID: 331882



Photo 7 – Crude Oil Tank