

Caerus Piceance LLC
RI1
Location # 334572



location




location

Caerus Piceance LLC
RI1
Location # 334572



location



location



Caerus Piceance LLC
RI1
Location # 334572



Location/ lack of battery signage



Missing cap

Caerus Piceance LLC
RI1
Location # 334572



Open ended piping for wildlife to enter



Previous inspection of Open ended piping for wildlife to enter



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
RI1
Location # 334572



Open ended piping for wildlife to enter



Open ended piping for wildlife to enter

Caerus Piceance LLC
RI1
Location # 334572



Open ended piping for wildlife to enter



Stored equipment/ debris



Caerus Piceance LLC
RI1
Location # 334572



Stored equipment/ debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources