

# Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334610

Location Name: BASS-67S93W/14SWNE

Inspection Document #: 702801039

Garfield County, CO

SWNE Section 14 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BASS-67S93W/14SWNE  
Location ID: 334610



**Photo 1.** Photo taken from the south shows an overview of the location.



Inspection Photos  
Location Name: BASS-67S93W/14SWNE  
Location ID: 334610



**Photo 2.** Photo shows trash (aerosol spray can) at the separators.



Inspection Photos  
Location Name: BASS-67S93W/14SWNE  
Location ID: 334610



Photo 3. Photos show production areas. Note lack of tank battery sign (left) required per Rule 605.e.



Inspection Photos  
Location Name: BASS-67S93W/14SWNE  
Location ID: 334610



**Photo 4.** Photo shows production areas.



## Inspection Photos

Location Name: BASS-67S93W/14SWNE

Location ID: 334610



**Photo 5.** Photos show interim areas to the northeast (left) and southeast (right) appear dominated by introduced perennial grasses and occasional native shrubs. Snow cover and dormant season prevented full vegetation assessment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801039