

Inspection Photos
Location: Carl R Deepe B1
Facility ID:



Photo 1 –

Photo 2 – Weeds over grown around the wellhead

Inspection Photos
Location: Carl R Deepe B1
Facility ID:



Photo 3 – Staining visible around the wellhead

Photo 4 –

Inspection Photos
Location: Carl R Deepe B1
Facility ID:



Photo 5 –



Photo 6 –

Inspection Photos
Location: Carl R Deepe B1
Facility ID:




Photo 7 –