

Inspection Photos
Location: Hladkey Header
Facility ID: 480738



Photo 1 – Weeds overgrown near the header

Photo 2 – No signage on stockpile

Inspection Photos
Location: Hladky O’Gorman Header
Facility ID:



Photo 3 – Liner is beginning to rip under the contaminated stockpile

Photo 4 –

Inspection Photos
Location
Facility ID:



Photo 5 –