



SITE INSPECTION FORM

LOCATION NE SW 29-36-59WFIELD LONE TREEOPERATOR HUCKABACOUNTY ADAMSLEASE AMOCO - UPRR - PETERSON #7

DATE OF INSPECTION BEFORE/DURING DRILLING _____

RIG _____ SURFACE CASING SIZE _____ DEPTH SET _____

BOP'S _____ RETURNS _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ CMT VOL _____

COMMENTS _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ HOLE OPEN? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____

WELLHEAD SYSTEM INSTALLED? _____

TANKS _____ HEATERS _____

SKIM PITS _____

LEASE SIGN: YES _____ NO _____ TANK I.D.: YES _____ NO _____ NA _____

COMMENTS _____

DATE OF AL/DA/PA INSPECTION 7/7/87DATE PLUGGED: 5/13/87PITS BACKFILLED: YES ☒ NO _____HOLE PLUGGED: YES ☒ NO _____SITE CLEAN: YES ☒ NO _____BOND RELEASE OK: YES ☒ NO _____HOLE MARKER: YES _____ NO ☒COMMENTS D-7 PULLING LAST DEADMAN - LOCATED NICELY LEVELLED - ~~SAID~~ ROUGH ABOUTSAID FARMER TAKING SMALL PILE GRAVEL DATE APD EXPIRED _____PA INSPECTION RESULTS: PASS(Y) ☒ FAIL(N) _____PERMIT # 75-858API # 05-001-07091INSPECTOR JJK