

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334801

Location Name: BENZEL-67S93W/1NESE

Inspection Document #: 702801051

Garfield County, CO

NESE Section 1 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BENZEL-67S93W/1NESE
Location ID: 334801



Photo 1. Photo shows a LOTO riser adjacent to the tank battery. Unused riser equipment must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801051

Inspection Photos
Location Name: BENZEL-67S93W/1NESE
Location ID: 334801



Photo 2. Photos show what appears to be four (4) unused risers.



Inspection Photos
Location Name: BENZEL-67S93W/1NESE
Location ID: 334801



Photo 3. Photos show an overview of the location from the northwest (left) and production areas (right).

Inspection Photos
Location Name: BENZEL-67S93W/1NESE
Location ID: 334801



Photo 4. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801051

Inspection Photos
Location Name: BENZEL-67S93W/1NESE
Location ID: 334801



Photo 5. Photo shows interim areas to the south appear dominated by introduced perennial grasses and sagebrush. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801051