

Inspection Photos  
Location Name: JJ#1  
Location ID: 322216



Photo 1 TNK BTRY Weeds/Debris around Tanks



Photo 2 Gauge hatch open

**Inspection Photos**  
**Location Name: JJ#1**  
**Location ID: 322216**




**Photo 3 Weed/debris around tanks and equipment**



**Photo 4 Weeds around tanks and equipment**



**Inspection Photos**  
**Location Name: JJ#1**  
**Location ID: 322216**



**Photo 5 Guy line anchor not marked.**