

# Final Reclamation Inspection

December 15, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 332898

Inspection Document #: 697504463

Weld County, CO

SWNW Section 3 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SHUR VIEW #22-3  
Location ID: 332898



**Photo 1.** Photo taken from the well location, facing West. Photo illustrates one of the two wells have been plugged; therefore, this is a well release on an active location.