

Inspection Photos

12/19/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #334075

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334075



December 19, 2022



December 19, 2022

Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the location from west, northwest, northeast to east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334075



Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334075



Photo 3: Photos examples showing various holes observed throughout the entire liner at the tank battery.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334075



Photo 4: Laramie tank on the north end of the Location. Operator/Contents label not legible from distance (yellow arrow). Capacity label not observed.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334075



Photo 5: Tank next to wellhead. Labeling no longer legible.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334075



Photo 6: Photo example of vegetation over interim areas. Perennial vegetation observed, however there are areas of the Location that are predominantly annual plant species. Additionally, perennial species observed largely introduced species.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334075



Photo 7: Weed debris accumulation at culvert.