

# Inspection Photos

12/19/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #334082

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #334082



**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the location from west, northwest, northeast to east.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #334082



**Photo 2:** See comment under photo 1.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #334082



December 19, 2022



December 19, 2022

**Photo 3:** Wellheads, separator equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #334082



**Photo 4:** Tank battery. Signage on site designates Location as a “H2S Location”. Arrow shows only wind direction indicator on the Location is in disrepair.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #334082



**Photo 5:** Location signage.

