

Inspection Photos

12/19/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #334104

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334104



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the location from west, northwest, northeast to east.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334104



December 19, 2022



December 19, 2022

Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334104



Photo 3: Signage at Location entrance. Emergency contact number no longer legible. Battery signage indicates presence of H₂S; H₂S signage at Location entrance not posted.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334104



Photo 4: Tank battery. Signage at battery indicates presence of H2S. Photo right shows Wind Direction Indicator on Location is not longer in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334104



Photo 5: Photo example showing holes observed throughout entire liner at the tank battery.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334104



Photo 6: H2S Scavenger tank. Wildlife protection devices to prevent wildlife access to the secondary containment of the "H2S Scavenger" tank missing or insufficient.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #334104



December 19, 2022



December 19, 2022

Photo 7: Photos taken from the former storage pad north of the Location. Photo shows areas have since been reclaimed, though vegetation observed above snow appears to be predominantly weedy plant species.