

Inspection Photos

12/19/2022

Operator: CAERUS PICEANCE LLC - 10456

Location #334365

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the location from east, southeast, southwest to west.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 3: Tank facility, southwest end of the Location. “Slop Tank #1”.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 4: Western Tank battery Facility. Photo right shows southern-most tank missing signage/labeling.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 5: Northeastern tank battery facility. Photo right shows tanks missing signage/labeling.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



December 19, 2022

Photo 6: Southeastern tank battery.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 7: Photos example showing two of the wind direction indicators. Photo left example of indicator that remains in proper functioning condition, though deteriorating. Indicator in photo right no longer in proper functioning condition.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 8: Photos show wildlife protection devices missing from secondary containment. Photo right also shows tank missing label information.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



December 19, 2022

Photo 9: Photo taken from the south east end of the Location. Photo shows unused fence equipment stored on Location.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #334365



Photo 10: Photo example showing cut slopes of the Location. Limited visibility due to snow cover, however stormwater and erosion control BMPs do not appear to have been implemented at slopes and stockpiles on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #334365



Photo 11: Location Signage

