

Final Reclamation Inspection

September 7th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 330938

Inspection Document #: 701900719

NENW Section 23 T6N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 1. 2020 aerial imagery of the well pad, access road and tank battery. Could not identify well pad access road from historical imagery.

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 2. Overview photo of the well pad taken at ground level from the northern edge facing south.

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with reference area (see photo #5)

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 5. Well pad reference area.

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 6. Overview photo of the tank battery taken at ground level from the northern edge facing south.

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 7. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 8. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery shows minimal crop establishment and does not appear consistent with the adjacent crop reference area.

Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 9. Tank battery reference area.



Inspection Photos
Location Name: J & L Farms 23-21
Location ID: 330938



Photo 10. Northern portion of tank battery access road remains unreclaimed.