

Final Reclamation Inspection

September 18th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 305304

Inspection Document #: 701900722

NESW Section 20 T6N R63W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wells Ranch 23-20
Location ID: 305304



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Wells Ranch 23-20
Location ID: 305304




Photo 2. Overview photo of the well pad and access road taken from the southern edge facing north using a drone. Note: well pad and access road appear consistent with the adjacent crop reference area.

Inspection Photos
Location Name: Wells Ranch 23-20
Location ID: 305304



Photo 3. Overview photo of the tank battery taken at ground level from the northern edge facing south.

Inspection Photos
Location Name: Wells Ranch 23-20
Location ID: 305304



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east. Note: gravel remains on site at access point.

Inspection Photos
Location Name: Wells Ranch 23-20
Location ID: 305304



Photo 5. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery falls within a corner crop area. Tank battery access point remains with gravel. Riser pictured is a DCP Midstream riser.