

Final Reclamation Inspection

October 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322652

Inspection Document #: 701900745

SENW Section 9 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bond 1
Location ID: 322625



Photo 1. 2020 aerial imagery of the well pad and tank battery.
Note: tank battery and well pad share a disturbance pad.



Photo 2. Overview photo of the well pad and tank battery taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Bond 1
Location ID: 322625



Photo 3. Cardinal photos taken at ground level from the middle of the well pad/tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Bond 1
Location ID: 322625



Photo 4. Cardinal photos taken at ground level from the middle of the well pad and tank battery. Left photo facing south, right photo facing west. Note: southern portion of the tank battery disturbance shows significant bare ground that is not consistent with adjacent reference area (see photo 5).



Photo 5. Well pad/tank battery reference area.