

Final Reclamation Inspection

October 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 330620

Inspection Document #: 701900746

SWNW Section 9 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Blosskas 12-9
Location ID: 330620



Photo 1. 2019 aerial imagery of the well pad, access road, and tank battery.



Inspection Photos
Location Name: Blosskas 12-9
Location ID: 330620



Photo 2. Overview photo of the well pad taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Blosskas 12-9
Location ID: 330620



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Blossas 12-9
Location ID: 330620



Photo 4. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with reference area (see photo 5).

Inspection Photos
Location Name: Blosskas 12-9
Location ID: 330620



Photo 5. Well pad reference area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900746

Inspection Photos
Location Name: Blossas 12-9
Location ID: 330620



Photo 6. Overview photo of the tank battery taken at ground level from the southern edge facing north. Note: tank battery remains unreclaimed with gravel.