

Final Reclamation Inspection

October 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 330621

Inspection Document #: 701900755

NENW Section 15 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 1. 2020 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 2. Overview photo of the well pad taken at ground level from the eastern edge facing west.

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621




Photo 4. Cardinal photos at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad is dominated by Kochia and does not appear consistent with adjacent reference area (see photo 5).

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 5. Well pad reference area.

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 6. Overview photo of the tank battery taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 7. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 8. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Loustalet 21-15
Location ID: 330621



Photo 9. Pit and large gravel pile remains at the tank battery location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900755