

Final Reclamation Inspection

October 20th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 327120

Inspection Document #: 701900757

SWNW Section 19 T5N R63W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 1. 2020 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 2. Overview photo of the well pad taken at ground level from the southern edge facing west. Note: well pad now resides in a cow pasture.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 4. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 5. Well pad access road remains with gravel and a culvert.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 6. Overview photo of the tank battery taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 7. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 8. Cardinal photos taken ground level from the middle of the tank battery. Left photo facing south, right photo face west.

Inspection Photos
Location Name: Johnson 2
Location ID: 327120



Photo 9. Tank battery access point remains with gravel.