

Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 431050

Location Name: Shideler/19-16C (O19EB)

Inspection Document #: 702801080

Garfield County, CO

SWSE Section 19 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shideler/19-16C (O19EB)
Location ID: 431050



Photo 1. Photo taken from the entrance shows an overview of the location.



Inspection Photos
Location Name: Shideler/19-16C (O19EB)
Location ID: 431050



Photo 2. Photos show production areas. Note lack of tank battery sign (left).



Inspection Photos
Location Name: Shideler/19-16C (O19EB)
Location ID: 431050



Photo 3. Photo shows production areas.



Inspection Photos
Location Name: Shideler/19-16C (O19EB)
Location ID: 431050




Photo 4. Photos show bull plugs not installed on tank drain line.



Inspection Photos
Location Name: Shideler/19-16C (O19EB)
Location ID: 431050




Photo 5. Photos show interim areas at the north (left). Portions of the interim areas appear poorly vegetated with perennials and dominated by annuals (left polygon and right). Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801080