

Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334886

Location Name: SHIDELER-67S92W/19SENE

Inspection Document #: 702801072

Garfield County, CO

SENE Section 19 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHIDELER-67S92W/19SENE
Location ID: 334886



Photo 1. Photos show production areas. Note lack of tank battery sign (left).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801072

Inspection Photos
Location Name: SHIDELER-67S92W/19SENE
Location ID: 334886



Photo 2. Photo shows production areas.



Inspection Photos

Location Name: SHIDELER-67S92W/19SENE

Location ID: 334886



Photo 3. Photos show open ended piping and bull plugs not installed at tanks.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801072

Inspection Photos

Location Name: SHIDELER-67S92W/19SENE

Location ID: 334886



Photo 4. Photos show rill erosion behind the separators.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801072

Inspection Photos

Location Name: SHIDELER-67S92W/19SENE

Location ID: 334886



Photo 5. Photos show interim areas at the west (left) and north (right) appear dominated by introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801072