

# Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 311615

Location Name: HMU-67S92W/19SWNE

Inspection Document #: 702801074

Garfield County, CO

SWNE Section 19 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HMU-67S92W/19SWNE  
Location ID: 311615



Photo 1. Photos show production areas. Note lack of tank battery sign (left).



Inspection Photos  
Location Name: HMU-67S92W/19SWNE  
Location ID: 311615



**Photo 2.** Photo shows production areas.



Inspection Photos  
Location Name: HMU-67S92W/19SWNE  
Location ID: 311615



Photo 3. Photos show open ended separator piping.

Inspection Photos  
Location Name: HMU-67S92W/19SWNE  
Location ID: 311615



**Photo 4.** Photo shows a plastic drain pipe (top) being bypassed by stormwater resulting in undermining and erosion beneath the pipe (bottom).

Inspection Photos  
Location Name: HMU-67S92W/19SWNE  
Location ID: 311615



**Photo 5.** Photos show interim areas at the east (left) and west (right) appear dominated by introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801074