

# Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334660

Location Name: SHIDELER-67S92W/30SWNW

Inspection Document #: 702801082

Garfield County, CO

SWNW Section 30 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SHIDELER-67S92W/30SWNW  
Location ID: 334660



**Photo 1.** Photo taken from the entrance shows an overview of the location.



Inspection Photos  
Location Name: SHIDELER-67S92W/30SWNW  
Location ID: 334660



**Photo 2.** Photos show production areas. Note lack of tank battery sign (left).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801082



## Inspection Photos

Location Name: SHIDELER-67S92W/30SWNW

Location ID: 334660



**Photo 3.** Photo shows production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801082

Inspection Photos  
Location Name: SHIDELER-67S92W/30SWNW  
Location ID: 334660



**Photo 4.** Photos show bull plugs not installed on tank drain line.



Inspection Photos  
Location Name: SHIDELER-67S92W/30SWNW  
Location ID: 334660



**Photo 5.** Photos show interim areas at the north of the location. Perennial grasses are present, however low residual cover from grazing and dormant season prevented full vegetation assessment.

