

# Inspection Photos

December 27, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334938

Location Name: SHIDELER-67S93W/25NWNE

Inspection Document #: 702801086

Garfield County, CO

NWNE Section 25 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SHIDELER-67S93W/25NWNE  
Location ID: 334938



**Photo 1.** Photo taken from the north shows an overview of the location.



Inspection Photos  
Location Name: SHIDELER-67S93W/25NWNE  
Location ID: 334938



**Photo 2.** Photos show bull plugs not installed on tank drain lines (left) and open ended piping at tank battery (right).

Inspection Photos  
Location Name: SHIDELER-67S93W/25NWNE  
Location ID: 334938



Photo 3. Photos shows open ended piping at separators.



Inspection Photos  
Location Name: SHIDELER-67S93W/25NWNE  
Location ID: 334938



**Photo 4.** Photo shows interim areas at the north of the location. Perennial grasses are present, however low residual cover from grazing and dormant season prevented full vegetation assessment.

