

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 323922

Location Name: CLOUGH-66S94W/29NENE

Inspection Document #: 702801105

Garfield County, CO

NENE Section 29 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/29NENE
Location ID: 323922



Photo 1. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801105

Inspection Photos
Location Name: CLOUGH-66S94W/29NENE
Location ID: 323922



Photo 2. Photos show degradation to the pad surface.

Inspection Photos
Location Name: CLOUGH-66S94W/29NENE
Location ID: 323922



Photo 3. Photo shows degradation to the access road to the west of the location.

Inspection Photos

Location Name: CLOUGH-66S94W/29NENE

Location ID: 323922



Photo 4. Photos show the access road culvert to the north (left) and south (right). No degradation observed in visible areas at the time of this inspection. Areas of previously observed rill erosion (arrow) are snow covered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801105

Inspection Photos
Location Name: CLOUGH-66S94W/29NENE
Location ID: 323922



Photo 5. Photo shows an example of the interim areas. Perennial grasses appear well established, however annual weeds also appear widespread.

