

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335122

Location Name: CLOUGH-66S94W/28NWNE

Inspection Document #: 702801107

Garfield County, CO

NWNE Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNE
Location ID: 335122



Photo 1. Photos show production areas.



Inspection Photos
Location Name: CLOUGH-66S94W/28NWE
Location ID: 335122




Photo 2. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801107

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNE
Location ID: 335122




Photo 3. Photos show the cut slope at the southeast of the location. BMPs have been installed at the base of the slope, which continues to erode. Photos show site degradation from undercutting, causing soil loss and exposed plant roots.



Inspection Photos
Location Name: CLOUGH-66S94W/28NWNE
Location ID: 335122



Photo 4. Photo shows the eroding cut slope at the southeast of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801107

Inspection Photos

Location Name: CLOUGH-66S94W/28NWNE

Location ID: 335122



Photo 5. Photos show scotch thistle (List B Noxious, left) and an example of interim areas well vegetated with perennial grasses (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801107