

Inspection Photos

API: 055-06157

Operator: PETROGLYPH OPERATING CO

Inspection Date: 1/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06157 | Date: 1/6/2023

Inspection Photos



Photo 1. Facing northwest at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 1/6/2023

Inspection Photos



Photo 2. There is an area of erosion along the former road which has not been repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 1/6/2023

Inspection Photos



Photo 3. Facing back southeast along the road where erosion occurred along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 1/6/2023

Inspection Photos



Photo 4. Facing northwest toward the location. Perennial vegetation has uniformly reestablished at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 1/6/2023