

Inspection Photos

STATE 36-05 BIG PIT

Operator: PETROGLYPH OPERATING CO

Inspection Date: 1/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 1/6/2023

Inspection Photos



Photo 1. Facing south at the beginning of the access road. There is erosion in this area nag vegetation has not fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 1/6/2023

Inspection Photos



Photo 2. There is an erosion channel along the former road. This needs to be repaired and reclaimed. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 1/6/2023

Inspection Photos



Photo 3. Facing south toward the Big Pit location. Perennial vegetation is progressing throughout this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 1/6/2023

Inspection Photos



Photo 4. Center of the Big Pit location. There are numerous noxious weeds (Scotch thistle) that have not been controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 1/6/2023

Inspection Photos



Photo 5. Facing north toward the reclaimed STATE 36-05 BIG PIT. Perennial vegetation is progressing throughout this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

STATE 36-05 BIG PIT | Date: 1/6/2023