

# Inspection Photos

ROHR #09-10 Big Pit

Operator: PETROGLYPH OPERATING CO

Inspection Date: 1/6/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** (East side of the road) Facing east toward reclaimed ROHR #09-10 Big Pit. The perennial vegetation is progressing since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06165 | Date: 1/6/2023

## Inspection Photos



**Photo 2.** (East side of the road) Facing southwest at the northeast disturbance area. This area is progressing but still consists of weedy areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06165 | Date: 1/6/2023

## Inspection Photos



**Photo 3.** The is pipe that remains at the northeast corner of the location.



**Photo 4.** There is also pieces of debris that remains at the east side of location.



## Inspection Photos



**Photo 5.** (West side of the road.) Facing south toward reclaimed ROHR #09-10 Big Pit. The perennial vegetation is progressing since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06165 | Date: 1/6/2023

## Inspection Photos



**Photo 6.** (West side of the road.) Facing northwest toward reclaimed ROHR #09-10 Big Pit. The perennial vegetation is progressing since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06165 | Date: 1/6/2023