

Inspection Photos
Location Name: Vicki 1
Location ID: 320538

Jan 4, 2023 at 2:22:48 PM
39.801991,-104.236279
Adams County
COGCC



Pic 1 Separator, weeds unmanaged

Jan 4, 2023 at 2:22:58 PM
39.802093,-104.236254
Adams County
COGCC



Pic 2 tanks, weeds unmanaged

Inspection Photos
Location Name: Vicki 1
Location ID: 320538

Jan 4, 2023 at 2:23:08 PM
39.802184,-104.236223
Adams County
COGCC



Pic 3 pit with steel pipe inside, needs cover

Jan 4, 2023 at 2:24:29 PM
39.802184,-104.236223
Adams County
COGCC



Pic 4 Pump jack needs to be removed from location

Inspection Photos
Location Name: Vicki 1
Location ID: 320538

Jan 4, 2023 at 2:25:37 PM
39.802198,-104.236734
Adams County
COGCC



Pic 5 wellhead, unable to drive to wellhead due to snow, and land owner plowing road.