

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 311583

Location Name: CLOUGH-66S94W/28NWNW

Inspection Document #: 702801111

Garfield County, CO

NWNW Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311583



Photo 1. Photo taken from the west shows an overview of the location.

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311583




Photo 2. Photos show equipment areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801111

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311583



Photo 3. Photos show lack of stabilization/compaction.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801111

Inspection Photos
Location Name: CLOUGH-66S94W/28NWNW
Location ID: 311583



Photo 4. Photo shows an example of the interim areas. Introduced perennial grasses appear established.