

Inspection Photos

January 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335309

Location Name: BONNEVILLE-66S94W/28NENW

Inspection Document #: 702801113

Garfield County, CO

NENW Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BONNEVILLE-66S94W/28NENW
Location ID: 335309



Photo 1. Photo taken from the south shows an overview of the location.

Inspection Photos
Location Name: BONNEVILLE-66S94W/28NENW
Location ID: 335309



Photo 3. Photos show lack of stabilization/compaction.



Inspection Photos
Location Name: BONNEVILLE-66S94W/28NENW
Location ID: 335309



Photo 2. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801113

Inspection Photos
Location Name: BONNEVILLE-66S94W/28NENW
Location ID: 335309



Photo 4. Photo shows an example of the interim areas. Introduced perennial grasses appear established.

