

# Inspection Photos

January 9, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335167

Location Name: Mead/30-11 Pad

Inspection Document #: 702801127

Garfield County, CO

NESW Section 30 T6S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mead/30-11 Pad  
Location ID: 335167



**Photo 1.** Photo taken from the south shows an overview of the location.



Inspection Photos  
Location Name: Mead/30-11 Pad  
Location ID: 335167



**Photo 2.** Photo shows a bull plug not installed.



**Location ID: 335167**



**Photo 3.** Photos show production areas.

Inspection Photos  
Location Name: Mead/30-11 Pad  
Location ID: 335167



**Photo 4.** Photo shows an example of interim areas. Native shrubs appear well established. Herbaceous species are less evident; assessment impeded by deep snow cover.

