

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403269380
Receive Date:
12/23/2022
Report taken by:
Steven Arauza

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>SUMMIT MIDSTREAM PARTNERS LLC</u>	Operator No: <u>200565</u>	Phone Numbers Phone: <u>(832) 6086137</u> Mobile: <u>(713) 2923472</u>
Address: <u>910 LOUISIANA ST STE 4200</u>		
City: <u>HOUSTON</u>	State: <u>TX</u>	Zip: <u>77002</u>
Contact Person: <u>Sherri Gregg</u>	Email: <u>sherri.gregg@summitmidstream.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 26805 Initial Form 27 Document #: 403269380

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>480936</u>	API #: _____	County Name: <u>GARFIELD</u>
Facility Name: <u>Gathering Line near PN30 pad</u>		Latitude: <u>39.405000</u>	Longitude: <u>-108.040000</u>
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: <u>NESW</u>	Sec: <u>30</u>	Twp: <u>7S</u>	Range: <u>95W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications GC Most Sensitive Adjacent Land Use Rangeland
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

The closest drainage is Dry Creek, an ephemeral stream, located 1120' south and 282' lower in elevation than the Site. Stock pond located 1925' NW of Site.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste** **Other E&P Waste** **Non-E&P Waste**
- Produced Water Workover Fluids
- Oil Tank Bottoms
- Condensate Pigging Waste
- Drilling Fluids Rig Wash
- Drill Cuttings Spent Filters
- Pit Bottoms
- Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	16D' X 30'L X 9'D	Visual, Excavation, Field Screening

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Site was excavated on January 26th 2022. For details please see the attached Investigation.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Entrada recommends the collection of produced water samples to understand the chemistry of the produced water in terms of Arsenic and pH.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 5 -- Highest concentration of TPH (mg/kg) 205.4
 Number of soil samples exceeding 915-1 5 -- Highest concentration of SAR 2.02
 Was the areal and vertical extent of soil contamination delineated? No BTEX > 915-1 No
 Approximate areal extent (square feet) 480 Vertical Extent > 915-1 (in feet) 9

Groundwater

Number of groundwater samples collected 0 Highest concentration of Benzene (µg/l) _____
 Was extent of groundwater contaminated delineated? No Highest concentration of Toluene (µg/l) _____
 Depth to groundwater (below ground surface, in feet) _____ Highest concentration of Ethylbenzene (µg/l) _____
 Number of groundwater monitoring wells installed _____ Highest concentration of Xylene (µg/l) _____
 Number of groundwater samples exceeding 915-1 _____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 _____ Number of surface water samples exceeding 915-1
 If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

- Were impacts to adjacent property or offsite impacts identified?

- Were background samples collected as part of this site investigation?
 A background sample was collected from a depth of 5 ft-bgs south of the spill area in an unimpacted area.
- Was investigation derived waste (IDW) generated as part of this investigation?
 Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____
- Is further site investigation required?
 Entrada recommends the collection of produced water samples to understand the chemistry of the produced water in terms of Arsenic and pH.

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.
 Gathering line was excavated and repaired.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.
 Remediation plan will be submitted once produced water samples have been collected and analyzed.

Soil Remediation Summary

- | | |
|---|---|
| <input type="checkbox"/> In Situ | <input type="checkbox"/> Ex Situ |
| _____ Bioremediation (or enhanced bioremediation) | _____ Excavate and offsite disposal |
| _____ Chemical oxidation | _____ If Yes: Estimated Volume (Cubic Yards) _____ |
| _____ Air sparge / Soil vapor extraction | _____ Name of Licensed Disposal Facility or COGCC Facility ID # _____ |
| _____ Natural Attenuation | _____ Excavate and onsite remediation |

Other _____

Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other _____

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator anticipates the remaining cost for this project to be: \$ _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation plan will be provided after remediation plan has been developed.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/26/2022

Proposed site investigation commencement. 02/01/2023

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

Soil analytical results of the January soil sampling event identified subsurface concentrations of arsenic and pH above the applicable COGCC Table 915 1 cleanup concentrations. All remaining sample results were compliant with the applicable COGCC Table 915 1 cleanup concentrations. Entrada recommends the collection of produced water samples to understand the chemistry of the produced water in terms of Arsenic and pH.

Based upon field screening and soil sampling activities completed at the site and laboratory analytical data presented herein, Entrada recommends that Summit file an initial form 27 remediation workplan with the COGCC. Once the Form 27 is approved, a request of closure of Form 19 (402844279) should also be filed.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Sherri Gregg

Title: Env Compliance Specialist

Submit Date: 12/23/2022

Email: sherri.gregg@summitmidstream.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Steven Arauza

Date: 01/13/2023

Remediation Project Number: 26805

COA Type**Description**

	Submit complete documentation of soil sampling events and disposal documentation for work completed to remediate impacts resulting from Spill/Release ID #480936 to date.
	Operator shall collect soil samples from areas most likely to be impacted and shall collect an appropriate number of representative soil samples to delineate the horizontal and vertical extents of contamination, per Rule 915.e.(2).B.
	Operator shall collect sample(s) from comparable, nearby non-impacted native soil for purposes of establishing background soil conditions for pH per Rule 915.e.(2).D. Operator may also include arsenic analysis to assess background soil conditions.
	Per Rule 913.b.(2), the Operator will conduct sampling and analysis of soil, and groundwater--if encountered, to determine the horizontal and vertical extent of any contamination in excess of the cleanup concentrations in Table 915-1 for soil and groundwater.
	Submit Supplemental eForm 19 to request closure of Spill/Release ID #480936. Supplemental report shall comply with outstanding COAs, indicate that work is proceeding under an approved eForm 27 and shall reference the Remediation Project number assigned upon approval of this report.
5 COAs	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403269380	FORM 27-INITIAL-SUBMITTED
403269622	REMEDICATION PROGRESS REPORT
403269627	PHOTO DOCUMENTATION
403270686	OTHER

Total Attach: 4 Files

General Comments**User Group****Comment****Comment Date**

Environmental	Updated this form to document the presence of surface water feature (Dry Creek) within 1/4-mile of the project area.	01/13/2023
---------------	--	------------

Total: 1 comment(s)