

Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334839

Location Name: COUEY-67S92W/8NWNW

Inspection Document #: 702801133

Garfield County, CO

NWNW Section 8 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: COUEY-67S92W/8NWNW
Location ID: 334839



Photo 1. Photo shows an overview of the location from the east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801133

Inspection Photos

Location Name: COUEY-67S92W/8NWNW

Location ID: 334839



Photo 2. Photos tank battery signage is absent (left) and the tank drain line bull plug is partially ajar/not properly installed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801133

Inspection Photos
Location Name: COUEY-67S92W/8NWNW
Location ID: 334839




Photo 3. Photos show production areas.



Inspection Photos
Location Name: COUEY-67S92W/8NWNW
Location ID: 334839



Photo 4. Photo shows an unmarked anchor at the northeast of the location.

Inspection Photos
Location Name: COUEY-67S92W/8NWNW
Location ID: 334839



Photo 3. Photo shows an example of interim areas. The vegetation community appears dominated by sparse rabbitbrush.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801133