

# Inspection Photos

January 9, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335486

Location Name: Benton/GV 15-36

Inspection Document #: 702801135

Garfield County, CO

SENW Section 36 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Benton/GV 15-36  
Location ID: 335486



Photo 1. Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801135

Inspection Photos  
Location Name: Benton/GV 15-36  
Location ID: 335486

1/9/23  
+39.485468,-107.839586  
93° E



**Photo 2.** Photo shows vehicles and other debris stored at the northeast of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801135

Inspection Photos  
Location Name: Benton/GV 15-36  
Location ID: 335486



**Photo 4.** Photo shows an example of interim areas. Perennial grasses appear established. One noxious thistle observed (inset).

