

Inspection Photos

January 9, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 323840

Location Name: BENTON-66S94W/36SEnw

Inspection Document #: 702801137

Garfield County, CO

SEnw Section 36 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC




COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BENTON-66S94W/36SENW
Location ID: 323840



1/9/23
-107.840860
90° E



Photo 1. Photos show production areas.




COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801137

Inspection Photos
Location Name: BENTON-66S94W/36SEW
Location ID: 323840



1/9/23
+39.485692,-107.840545
277° W

Photo 2. Photo shows a bull plug is not installed on the tank drain.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801137

Inspection Photos
Location Name: BENTON-66S94W/36SENW
Location ID: 323840



Photo 3. Photos show the wildlife protection netting is not in proper functioning condition due to being weighed down by snow.

Inspection Photos
Location Name: BENTON-66S94W/36SEW
Location ID: 323840



Photo 4. Photo shows a leaking corrosion inhibitor tank and stained soils.



Inspection Photos
Location Name: BENTON-66S94W/36SENW
Location ID: 323840



Photo 5. Photo shows interim areas appear vegetated with perennial grasses.

