

Inspection Photos

API: 071-09267

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/17/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09267 | Date: 1/17/2023

Inspection Photos



Photo 1. Facing toward the wellsite. Sign has been posted at the pit for In process for closure.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 1/17/2023

Inspection Photos



Photo 2. There are holes in the pit liner which need to be replaced. The water level at the pit has not been lowered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 1/17/2023

Inspection Photos



Photo 3. There are holes in the pit liner which are at the water level.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 1/17/2023

Inspection Photos



Photo 4. The well signs are posted at the meter shed. Stained soils have been cleaned up and a secondary container was installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09267 | Date: 1/17/2023