



99999999

WELL SITE INSPECTION FORM



Well Name MankaTM 1 API Number 05 - 081 - 053260
Operator Hondo Oil & Gas Co. Permit # _____
Location NW SW 23 - 6N - 90W County Mottat
Field Buck Creek Inspector BSM
AL/PA/DA Inspection Results: Well Status:
Pass (Y) X Fail (N) _____ Date 9/21/90 FN _____ FD _____ WO _____ PR _____ SI _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Contact _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 12/31/62 Date Permit Expired: _____
Hole Plugged: Yes X No _____ Pits Backfilled: Yes _____ No X
Material Buried: Yes X No _____ N/A _____ Site Clean: Yes X No _____
Bond Release OK: Yes X No _____ Fed _____ Hole Marker: Yes _____ No X

Date of Safety/Status Inspection _____

Comments: Pits not backfilled, But hole was plugged 28 years ago, so thick sagebrush has overgrown everything.



00213285

Violations: Yes _____ No X Notice Sent: Yes _____ No X Date Sent: _____