

Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334872

Location Name: SAMPLE-67S92W/17SE17W

Inspection Document #: 702801157

Garfield County, CO

NWSE Section 17 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SAMPLE-67S92W/17SENW

Location ID: 334872



Photo 1. Photo taken from the west shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801157

Inspection Photos

Location Name: SAMPLE-67S92W/17SEW

Location ID: 334872



Photo 2. Photos show production areas. No tank battery sign is present (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801157

Inspection Photos

Location Name: SAMPLE-67S92W/17SEW

Location ID: 334872



Photo 3. Photos shows a bull plug not installed on the tank drain (left) and wildlife protection BMPs are absent on the produced water secondary containment tank (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801157

Inspection Photos

Location Name: SAMPLE-67S92W/17SEW

Location ID: 334872



1/13/23
+39.444812,-107.686821
327° NW



Photo 4. Photos show the western (left), eastern (right) and center (inset) soil piles at the north of the location. Wattles are installed around each pile. No control measures observed to prevent contaminated stormwater from leaving the Land Treatment area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801157

Inspection Photos

Location Name: SAMPLE-67S92W/17SE

Location ID: 334872



Photo 5. Photos show degradation to the pad surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801157