

Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334680

Location Name: SHAEFFER-67S93W/12NWNW

Inspection Document #: 702801158

Garfield County, CO

NWNW Section 12 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHAEFFER-67S93W/12NWNW
Location ID: 334680



Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos

Location Name: SHAEFFER-67S93W/12NWNW

Location ID: 334680



Photo 2. Photos show production areas. Excavations at the separator and wellhead are for decommissioning of plugged and abandoned well API # 045-09133 and the associated flowline.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801158

Inspection Photos

Location Name: SHAEFFER-67S93W/12NWNW

Location ID: 334680



Photo 3. Photos show soil stockpiles from the plugged and abandoned well (left) and flowline (right) excavations. Excavated soil is surrounded by a berm of loose, unconsolidated soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801158

Inspection Photos

Location Name: SHAEFFER-67S93W/12NWNW

Location ID: 334680



Photo 4. Photo shows an example of location interim areas. Introduced perennial grasses appear established.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801158